



**ISU-710D
UT THICKNESS GAUGE
OPERATION MANUAL**



Attention

- ◆ In order to obtain good measurement precision, you need to clear away the rusty, sundry, grease, etc. on the working surface.
- ◆ Please use the couplant on the working surface, measure repeatedly around the target area and take average value.
- ◆ Please clean the couplant on the transducer and working surface after measure.
- ◆ Please don't pull the transducer cable when use the instrument.
- ◆ Please don't apply couplant to the transducer before turning on.

Description

ISU-710D is a visual A/B scan ultrasonic thickness gauge with high energy. It is a Multi-Mode thickness gauge that has the ability to measure every thick composite material or material that is very hard for ultrasonic to go through. This unit can measure the thickness of metallic and non-metallic materials such as steel, aluminum, titanium, plastics, ceramics, glass and any other good ultrasonic wave conductor.

The unit comes with following features:

- Large color TFT display
- Automatic probe recognition
- Automatic probe zero calibration
- Automatically locates the detection point if the measurement is out of the viewable display area.
- Allow user to adjust the range of GAIN, RANGE, DELAY, GATE, BLANK, E-BLANK in manual-measurement mode
- Limitation setting, alarm with sound and display
- Multi-languages
- Memory of 100 files X 100 data, transfer data to PC without software, available for any windows operating systems
- Measurement screen automatic frozen, which make it easy to analyze the data for the user.

Technical Specifications

Measurement range	T-E:20mm~590mm
Resolution	0.01mm(0.001inch), 0.1mm (0.01inch)
Velocity range	1000m/s~9999m/s
Measurement rate	2/s and 10/s in fast mode
Average mode	2 to 9 times average measurement
Limited setting	With Low-high indication and alarm
Measuring Units	mm / inch
Data output	USB to PC without software
Display	320×240 TFT Color LCD
Battery	2 x AA Batteries
Operating	-20°C~+50°C
Memory	Memory of 10,000 readings in 100 files
Dimensions	133mm(L)×75mm(W)×29mm(H)
Weight	0.26kg(including batteries)

Overview




Keypad Functions



- 
On & Off Key Function 1: It is used to power the unit either ON or OFF.
 Function 2: Pressing this key to escape the menu setting and return back to the main measurement screen.
- 
Menu Key Function 1: It is used to enter the menu and confirm the selection.
 Function 2: It is as a shortcut key in A-scan mode. After finish one A-scan measurement (keeping the Parameters field in highlight), press this key to store the current set-up parameters into the CUSTOM SETTING.
- 
F1 Key Function 1: In A-scan manual mode, it is a toggle button mainly used to set up the parameters RANGE, GAIN, DELAY, GATE, BLANK by adjusting the key 
 Function 2: In B-scan mode, press this key to clear current graph and ready for next measurement.
- 
F2 Key Function 1: Press this key to toggle between display view options- A-Scan, B-SCAN and DIGITS.
 Function 2: In A-scan mode, press this key to save current custom setup that has been modified or created by the user.
- 
UP key Function 1: It is used to navigate the menus and increase values while setting the parameters.
 Function 2: In measurement mode, press this key to store the current measurement reading.

- 
DOWN key Function 1: It is used to navigate the menus and decrease values while setting the parameters.
 Function 2: In the measurement mode, it is used as the calibration Key. Put the probe in the air, press this key to complete the calibration.
- 
LEFT Key Function 1: It is used to navigate the menus and decrease values while setting the parameters.
 Function 2: In A-SCAN mode, press this key to enter CUSTOM SETTING screen to open a setup that has been saved before.
 Function 3: In B-Scan mode, press this key to control the thickness reading indicator(the small yellow triangle).
- 
RIGHT Key Function 1: It is used to navigate the menus and increase values while setting the parameters.
 Function 2: In DIGIS and A-SCAN mode, the readout will be changed between mm to inch by pressing this key.
 Function 3: In B-Scan mode, press this key to control the thickness reading indicator(the small yellow triangle).


Display Screen



1. Thickness reading - Digital readout of thickness. Display with white color means in testing, with blue color means frozen.
2. The 1st back wall indicator - The Red ▼ indicates the first back wall.

3. Gate indicator - The red line can be adjusted up or down.
4. Full waveform - Display with green color means in testing, with blue color means In frozen.
5. Blank indicator - The length of Red line changes with the BLANK number adjusted.
6. Delay value indicator
7. Parameters field - Gain, Delay, Blank, E-blank, Range adjustable
8. Memory location - Files 100 X 100 data can be stored
9. Transducer model - The transducer automatically recognizes and display
10. Velocity
11. End of Range indicator
12. Power life
13. Measuring mode
14. Measuring unit- millimeters or inches


BIG DIGITS MODE



1. Velocity
2. Transducer model - The transducer automatically recognizes and display
3. Measuring mode
4. Thickness Reading - Digital readout of thickness. Display with white color means in testing, with blue color means frozen.

5. Gain value - Can be adjusted from 10-50
6. Power life
7. Measuring unit - millimeters or inches
8. Memory location - Files 100 X 100 data can be stored
9. Hot menu indicators - Press the corresponding button, easy to cover the display or function.

B-SCAN MODE



1. Thickness reading - Digital readout of thickness. Display with white color means in testing, with blue color means frozen.
2. Min. value indicator - Indicates where the minimum is located.
3. B scan graphic
4. Thickness reading indicator - Indicates where the current thickness reading is Located.
5. Gain value - Can be adjusted from 10-50.
6. Velocity
7. Transducer model - The transducer automatically recognizes and display.
8. Power life – Generally 48 hours continuous work
9. B scan display range - Displays the range set in the menu and auto divides into 5 equal parts.
10. Min. value reading - Displays the minimum value of workpiece.
11. Hot menu indicators - Press the corresponding button, easy to convert to the display or function.

Quick startup guide

Step one: Selecting the Transducer and Probe zero & calibration
 Plug in the suitable transducer; turn on ISU-710D by pressing the  Key.

The gauge does auto calibration of the transducer, thus eliminating the need for an on-block zero. After turning on the gauge, the screen flashes the Series No, and software version, and then, it comes into the measurement mode directly. If user turning on the unit without the transducer, screen will remind to "Plug in the probe". At this moment, please insert a transducer into the socket, the gauge directly comes into the measurement mode after Auto calibration.

Notice: Please use the standard transducer offered; otherwise the unit does not work normally and displaying "Error". If users feel the thickness reading is incorrect during the measurement, please put the probe in the air, and press  for zero calibration at any time.

Note: For auto calibration, make sure the transducer is not coupled to the test piece when the gauge is first turned on and that there is no couplant on the end of the transducer. The transducer should also be at the room temperature, clean without any noticeable wear.

Step Two: Treatment of the measured surface

When the surface to be measured is too rough or rusty heavily, please perform the treatment according to the following methods:

1. Clean the measured surface by grinding, polishing or filing, etc. or use coupling agent with high viscosity for that.
2. Use coupling agents on the workpiece surface to be measured.
3. Take multiple measurements around the same testing point.

Step Three: Setting velocity

Sound velocity plays an important role in measurement. Different material is of different sound velocity. When the sound velocity is incorrect, it will cause wrong measured results. There are 3 ways to set the material's sound velocity, which are:

1. Directly select preset material velocity. Please refer to 2.1.2 on page 13.

2. Input the new velocity which is not preset into the menu. Please refer to 2.1.3 on page 14.

3. Get the accurate sound velocity of the workpiece which the thickness is known. Please refer to 2.1.4 on page 15.

Step Four: Measurement

The ISU-710D is now ready to measure. There are four different measurement view options, A-Scan RF+, A-Scan HALF+, B-Scan and DIGITS, each with a specific purpose.

A-Scan RF+: It shows both the positive and the negative peaks.

A-Scan HALF +: It shows the positive.

B-Scan: It displays a time based cross section view of test material.

DIGITS: It is a basic digital thickness gauge look and feel. The color and larger digits make it much easier for the operator to monitor the thickness readings.


User can toggle between the different view mode options by pressing .

MENU

1 MEA. (Measurement)

ISU-710D provides two measurement modes, T-E mode and E-E mode.



- 1) Press the  key to illuminate MEA.
- 2) Press  or  to select T-E or E-E mode, Press  to confirm.



Note: The E-E (echo-echo) function is not available owing to suitable probe is under developing right now.


T-E Mode

Measurement modes of Standard, Minimum, Difference, Average and limitation can be selected.



1.1 Standard Measurement:

With this function, the unit displays the current measurement value, satisfied with the normal measuring needs.




The following pages outline how to enable and set up this feature.

- 1) Press the key to illuminate MEA.
- 2) Use keys to scroll through the sub menu items until Standard is highlighted. Press the key to confirm.
- 3) Press the key to exit setting and ISU-710D is now ready to perform measurements.

1.2. Minimum Measurement:

When taking measurements, ISU-710D displays the smallest thickness reading it tests. It is suitable for testing the curvature surface or needs to get the minimum value which is widely used in the measurement of pipeline.

Notice: it is not recommended to use this function when measuring cast iron or alloy materials.




The following pages outline how to enable and set up this feature.

- 1) Press the key to illuminate MEA.
- 2) Use keys to scroll through the sub menu items until Minimum is highlighted. Press the key to confirm.
- 3) Press the key to exit setting and ISU-710D is now ready to perform measurements.


1.3. Difference mode:

In the quality Control environment, it is sometimes necessary to know the difference between a nominal (target) thickness value and an actual thickness value. With the Difference mode enabled, ISU-710D will display the positive (+) or negative(-) difference from an entered nominal value.



The following pages outline how to enable and set up this feature.

- 1) Press the key to illuminate MEA.
- 2) Use keys to scroll through the sub menu items until Difference is highlighted. Press the key to confirm. The Display shows as follows:




- 3) Press the key to move the cursor
- 4) Press the key to change the numbers and Dot position. The value could be set as 0.000, 00.00 and 000.00. The 1st and the last position can be set numbers 1-9 as a circle. The 3rd positions can be set numbers 1-9 and dot as a circle.
- 5) Press the key to confirm.
- 6) Press the key to exit setting and ISU-710D is now ready to perform measurements.

Notice: 500.0 is the Max. value can be set. If User sets the value exceeding the max. value, the unit will correct it as 500.0 automatically.


1.4. Average mode:

With this function, ISU-710D displays the average value of 2 to 9 measured points. It can help user to check the surface planeness of flat board and their manufacturing process.



The following pages outline how to enable and set up this feature:


- 1) Press the key to illuminate MEA.
- 2) Use keys to scroll through the sub menu items until **Average** is highlighted. Press the key to confirm. The Display shows as follows:



- 3) Press the or key to change the numbers among 2 to 9.
- 4) Press the key to confirm.
- 5) Press the key to exit setting and ISU-710D is now ready to perform measurements.


1.5. Limitation Mode

This function allows users to set an audible and visual (Hi/Lo) parameter when measurements. If the measurement falls below or above the HI/LO limits, set by the user, the red H or green L will be displayed and the beeper sounded. This improves the speed and efficiency of the inspection process by eliminating constant viewing of the actual reading displayed.



The following pages outline how to enable and set up this feature:


- 1) Press the key into MEA.
- 2) Use keys to scroll through the sub menu items until **Limitation** is highlighted. Press the key to confirm. The display shows as follows:



- 3) Use keys to set the low / high limitation. The value could be set as 0.000, 00.00 and 000.00. The 1st and the last position can be set numbers 1-9 as a circle. The 3rd positions can be set numbers 1-9 and dot as a circle. Press the key to confirm.
- 4) Press the key to exit setting and ISU-710D is now ready to perform measurements.

2 SET


This function allows users to set following parameters of measurement.



The following pages outline how to enable and set up these parameters.

2.1 Velocity rate

Sound velocity plays an important role in measurement. Different types of material have different inherent sound velocities. If the gauge is not set to the correct sound velocity, all of the measurements the gauge makes will be erroneous by some fixed percentage.




If the name or sound-velocity of the material to be measured is known, users could select material name directly in the menu **Materials**. Or input the known velocity in the menu **Velocity Input**. And users could measure the sound velocity by using the function **Velocity measurement** if the sound-velocity of the material to be measured is unknown, but the exact thickness of which is known.

1. Materials

The ISU-710D presets 9 common materials' sound velocity. They are: aluminum, titanium, steel, stainless steel, glass, copper, cast iron, brass, polystyrene.

Users may opt to choose such basic material type from the menu. It's important to note that these velocities will not always be an exact representation of the material being tested. Use these values only if close approximation is acceptable.




The following pages outline how to enable and set up this feature:

- 1) Press the key to illuminate **SET-Velocity rate-Materials**.
- 2) Use keys to scroll through the sub menu items until The target material is highlighted. Press the key to confirm.
- 3) Press the key to exit setting and ISU-710D is now ready to perform measurements.


2. Velocity input

If the material velocity is known, users may wish to simply enter the velocity value into ISU-710D, rather than have the ISU-710D calculate the velocity value on using a known thickness. And ISU-710D also can store 4 new velocities as custom.



The following pages outline how to enter the velocity:

- 1) Press the key to illuminate **SET-Velocity rate**.
- 2) Use keys to scroll through the sub menu items until VELOCITY INPUT is highlighted. Press the key to confirm.
- 3) Press the or key to move the cursor, Press the or Key to change the numbers.
- 4) Press the key to confirm and store it into Velocity Storage.



- 5) Press the or key to illuminate the place where want to store, Press the key to confirm.


- 6) Press the key to exit setting and ISU-710D is now ready to perform measurements.

3. Velocity measurement

Sometimes the sound velocity of a material is not known. In this case a sample with a known thickness can be used to determine the sound velocity. It would be very handy to carry a set of mechanical calipers to use in conjunction with the ISU-710D in the field.

The following steps outline how to enable and set up this feature:

- 1) Physically measure an exact sample of the material or a location directly. On the material to be measured using a set of calipers or a digital micrometer.
- 2) Apply a drop of couplant on the transducer and place the transducer in steady contact with the sample or actual test material.
- 3) The display should show a thickness reading (probably incorrect).
- 4) Having achieved a stable reading, remove the transducer. (If the Displayed thickness changes from the value shown while the transducer Was coupled, repeat step 3.)
- 5) Press the key to illuminate **SET**, Use keys to scroll through the sub menu items until Velocity Measurement is highlighted. Press the key to confirm.




- 6) Press the or key to move the cursor, press the or key to adjust the displayed velocity up or down, until the thickness value displayed matches the thickness of the sample piece. And now the displaying sound velocity value is accurate.

- 7) Press the key to confirm and store it into Velocity Storage.
- 8) Press the or key to illuminate the target place, Press the key to confirm.

9) Press the **ESC** key to exit setting and ISU-710D is now ready to perform measurements.

4. Velocity storage

It allows user to store 4 new Velocity locations as custom and use it in future measurement. Users can get the custom velocities by the features of Velocity input or Velocity measurement.



The following steps outline how to enable and set up this feature:


- 1) Press the **SET** key to illuminate SET-VELOCITY RATE.
- 2) Use **↑↓←→** keys to scroll through the sub menu items until Velocity storage is highlighted. Press the **SET** key to confirm.
- 3) Press **↑↓** key to illuminate the target velocity, Press **SET** to confirm.
- 4) Press **ESC** to exit setting and ISU-710D is now ready to perform measurements.

2.2 Resolution

Users can select the displayed resolution. When 0.01mm or 0.001 inch be selected, the workpiece surface to be measured should be smooth for the purpose of getting an accurate value.

The following pages outline how to enable and set up this feature:

- 1) Press the **SET** key to illuminate SET.
- 2) Use **↑↓←→** keys to scroll through the sub menu items until Resolution is highlighted. Press the **SET** key to confirm.
- 3) Press **↑↓** key to select resolution and unit. Press **SET** to confirm.



4) Press the **ESC** key to exit setting and ISU-710D is now ready to perform measurements.

2.3 Probe Calibration


It causes error during the primary stage of usage or operates for long time. Users should make probe calibration during following three aspects are happened.

1. The probe itself or the temperature variation,
2. System error caused by the match between the unit and the transducer.
3. Calculation error caused by the sound velocity set in the unit is different from that of the actual material.

This feature requires a sample piece of the specific material to be measured, the exact thickness of which is known. E.g. from having been measured by some other means. Or to use the build-in standard test block (4MM) comes with ISU-710D.

The following steps outline how to enable and set up this feature:


- 1) Apply a drop of couplant on the transducer and place the transducer in steady contact with the sample or standard test block.
- 2) Having achieved a stable reading, remove the transducer.
- 3) Press the **SET** key to illuminate SET, Use **↑↓←→** keys to scroll through the sub menu items until Probe calibration is highlighted. Press the **SET** key to confirm.



- 4) Press the **↑↓** or **←→** key to adjust the displayed reading up or down, until the thickness value displayed matches the thickness of the test block or sample piece. Press the **SET** key to confirm.
- 5) Press the **ESC** key to exit setting, Test the block or sample piece again to verify the result.

2.4 Measurement rate

The ISU-710D performs measurement of 2 times/second and 10 times/second. 2 times/second is quite adequate for single measurements. And 10 times/second is recommended to measure the high temperature surfaces.





The following steps outline how to enable and set up this feature:

- 1) Press the **SET** key to illuminate SET
- 2) Use **↑**, **↓**, **←**, **→** keys to scroll through the sub menu items until **Measurement rate** is highlighted.
- 3) Press the **↑** or **↓** key to select 2 times/S or 10 times/S. Press the **SET** key to confirm.
- 4) Press the **ESC** key to exit setting and ISU-710D is now ready to perform measurements.

Notice: When users remove the probe, screens shows average value according to the set by users.

2.5 Auto measurement

This feature is recommended to measure some basic materials. All parameters are preset according to the different transducers. For A-scan mode, it is a convenient way to let ISU-710D find the detection point and bring the waveform signal into view automatically.



The following steps outline how to enable and set up this feature:

- 1) Press the **SET** key to illuminate SET
- 2) Use **↑**, **↓**, **←**, **→** keys to scroll through the sub menu items until **Auto measurement** is highlighted. Press the **SET** key to confirm.
- 3) Press the **SET** key to confirm.
- 4) Press the **ESC** key to return to the measurement screen and began taking readings. There is Auto displayed on the left down corner of screen.


2.6 Manual measurement

This feature allows users to make fine adjustment of RANGE, GAIN, DELAY, GATE, BLANK, and E-BLANK manually in A-SCAN mode. They can be set through toggle the HOT MENUS what is displayed at the lower left side of the screen.

And once the above mentioned parameters are set, it will remain the same for B-SCAN and DIGITS display.

Range

The range refers to the overall viewable range being displayed on the screen. Make change the range of display, shorten or enlarge it, finally serve User conveniently. The following steps outline how to enable and adjust the RANGE.



- 1) Press **F1** once to illuminate RANGE.
- 2) Use keys **↓** (+1), **↑** (-1), **←** (-coarse adjustment), **→** (+coarse adjustment) to adjust value.


Gain

The gain can be set over a wide range. The setting of the gain is crucial in order to obtain valid reading during the measurement process. Too much gain may result in erroneous measurements, by detecting on noise rather than the actual material back wall itself. Too little gain may result in detection on an undesirable section of the waveform.

The gain will also be represented in both the BSCAN and DIGITS views.

The following steps outline how to enable and adjust the GAIN.


- 1) Press **F1** once to illuminate GAIN.
- 2) Use keys **↑** (+1), **↓** (-1), **←** (-coarse adjustment), **→** (+coarse Adjustment) to adjust value.



Delay

The starting DELAY is the value displayed on the bottom lower left side of the display in both RF+ and HALF+ views. It is the minimum thickness value that can be viewed on the display.


The following steps outline how to enable and adjust the DELAY.



- 1) Press **Fn** once to illuminate DELAY.
- 2) Use keys **▲** (+1), **▼** (-1), **◀** (-coarse adjustment), **▶** (+coarse adjustment) to change value.

Gate

GATE is used in both T-E and E-E modes. The purpose of GATE is to force ISU-710D to measure the useful echo wave. The following steps outline how to enable and adjust the GATE.




- 1) Press **Fn** once to illuminate GATE.
- 2) Use keys **▲** (+1), **▼** (-1), **◀** (-coarse adjustment), **▶** (+coarse adjustment) to adjust value.

Blank

BLANK is used in T-E mode. Make change of Blank to conceal those useless echoes that influence measuring result. When making changes, the red line at the left bottom corner changes accordingly. Users could take it as for reference and achieve the best measuring effect.

The following steps outline how to enable and adjust the BLANK.



- 1) Press **Fn** once to illuminate BLANK.
- 2) Use keys **▲** (+1), **▼** (-1), **◀** (-coarse adjustment), **▶** (+coarse adjustment) to adjust value.

Saving the setting

Once all the parameters are set, there is two ways to save the setting.


- 1) The user can Press **Fn** to store this setting into the current location.

When turn on the gauge next time, this setting will be displayed.

- 2) Or the user can Press **Esc** to store this setting into the A-SCAN CUSTOM SETTING for further use while measuring the same workpiece.


2.7 Rectification

ISU-710D supply two display views of A-scan. RF+ mode shows both the positive and the negative peaks. HALF+ mode shows the upper of complete waveform only.




The following steps outline how to select the RECTIFICATION.

- 1) Press the **Fn** key to illuminate SET
- 2) Use **▲▼** keys to scroll through the sub menu items until RECTIFICATION is highlighted. Press the **Fn** key to confirm.
- 3) Press **▲▼◀▶** key to select RF+ or HALF+,
- 4) Press **Fn** to confirm and return to the measurement screen and begin taking readings.



RF+



HALF+

2.8 A-SCAN custom setting

ISU-710D can store 4 A-SCAN custom settings. This feature saves a great deal of time and knowledge for future inspection of the same job or project. Also it eliminates error between two or more users during the setup and calibration process.

MEA. SET. MEM. FUN.	Memory read	F 001 004/100
Set a new file	Input file No.	001
Memory read	File 001	41.42 mm
Delete a file		5920 m/s
Delete all files		S1025 STD
Data transfer		

3.3 Delete a file

- 1) Press the key to illuminate MEM.
- 2) Use keys to scroll through the sub menu items until Delete a file is highlighted. Press the key to confirm.
- 3) Press to move the cursor, Press to set the target File Number. Press to confirm.

MEA. SET. MEM. FUN.	Delete a single file	Delete a single file
Set a new file	Input file No.	Yes
Memory read	File 001	No
Delete a file		
Delete all files		
Data transfer		

- 4) Use keys to select YES or NO, press key to confirm.

3.4 Delete all files

- 1) Press the key to illuminate MEM.
- 2) Use keys to scroll through the sub menu items until Delete all files is highlighted. Press the key to confirm.

MEA. SET. MEM. FUN.	Delete All files
Set a new file	Yes
Memory read	No
Delete a file	
Delete all files	
Data transfer	

- 3) Use keys to select YES or NO, press key to confirm.

3.5 Data Transfer

Users can input the measurement results into Excel, Word files for further analysis, which is equivalent to keyboard input. The operation is as follows:

- 1) Use the USB cable in the standard configuration to connect the machine to the PC, and create a new Excel or Word file on the computer.
- 2) After the real-time measurement is completed, press the key , the data will be output to the computer and automatically wrap.
- 3) Users can perform further analysis on real-time data.

4 FUN.

It allows user to adjust following functions:

MEA. SET. MEM. FUN.
Switch off mode
Languages
Contrast
Default
Information

4.1 Switch off mode

Auto shut down after 1 Min. 3 Min. 5 Min. can be selectable.

MEA. SET. MEM. FUN.	Switch off mode
Switch off mode	1 minute
Languages	3 minutes
Contrast	5 minutes
Default	
Information	

4.2 Languages

The gauge provides multi-languages for selection.

MEA. SET. MEM. FUN.	Languages
Switch off mode	English
Languages	Español
Contrast	Portugués
Default	
Information	

4.3 Contrast

Users can adjust contrast of display.

MEA. SET. MEM. FUN.	Contrast
Switch off mode	35
Languages	- [] +
Contrast	
Default	
Information	

4.4 Default

During the usage, when users can not ensure why the problems comes out and with some questions on setting, he can use this function to make the parameters to restore the factory status to eliminate any abnormal because of the parameters setting.

MEA. SET. MEM. FUN.	MEA. SET. MEM. FUN.	Default
Switch off mode	Switch off mode	Yes
Languages	Languages	
Contrast	Contrast	
Default	Default	No
Information	Information	

Measuring technology

◆ Measuring methods

The unit provides many measuring methods.

1. Single point measuring method: use the probe to measure any point of the workpiece to be measured and the displayed value is the thickness.
2. Two point measuring method: Perform two measurements on the same point of the measured surface, in the second measurement, splitting plane of the probe should be 90 degree, take the minimum as the thickness value.
3. Multiple point measurement method: perform several measurements in a circle about 30mm in diameter and take the minimum value as the thickness value.
4. Continuous measurement methods: apply the single point Measurement method, and take measurements continuously along the designated route, the intervals should be less than 5mm, and take the minimum value as the workpiece's thickness.

◆ Pipeline measurement method

During the measurement, make the probe's crosstalk interlayer plate be perpendicular or parallel to the axial line of the pipeline. For a pipeline with larger diameter, the probe's crosstalk interlayer plate should be perpendicular to the axial line of the pipeline, but for pipeline with small diameter, User should perform measurements making the crosstalk being both parallel and perpendicular to the axial line of the pipeline and take the minimum readout as the thickness value.

Maintenance and precautions

◆ Power check

When the power is low, the low battery indicator will appear, at this moment User should replace the battery in time, or it will affect the measuring accuracy. The backlight cannot be switched on for a long time, because it is a big consumer of electricity.

Note: if the unit did not used for a long time, please take out of the battery to avoid leakage to damage the unit.

◆ Precautions

1. General precautions

The unit should avoid strong vibration, do not let it in an excessively humid environment, plug in or out the probe should hold the jacket to avoid the core wire of the probe damaged.

2. Precaution during the measuring

- a. During the measurement, only the measuring icon appears and displayed stable, it can be regarded as a good measurement.
- b. If there are large quantity coupling agents attached on the measured surface, when taking away the probe, it will cause error, so when the measurement is completed, please move the probe away from the measured surface quickly.
- c. If the probe wears out, it will cause the displayed value unstable, please replace the probe.

APPENDIX : Sound Velocity Measurement Chart

Material	M/s	Inch/μs
Air	330	0.013
Aluminum	6300	0.250
Alumina Oxide	990	0.390
Beryllium	12900	0.510
Boron Carbide	11000	0.430
Brass	4300	0.170
Cadmium	2800	0.110
Copper	4700	0.180
Glass(crown)	5300	0.210

Material	M/s	Inch/μs
Glycerin	1900	0.075
Gold	3200	0.130
Ice	4000	0.160
Inconel	5700	0.220
Iron	5900	0.230
Iron (cast)	4600	0.180
Lead	2200	0.085
Magnesium	5800	0.230
Mercury	1400	0.057
Molybdenum	6300	0.250
Polyurethane	1900	0.070
Polythylene	1900	0.070
Polystyrene	2400	0.093
Quartz	5800	0.230
Rubber, Butyl	1800	0.070
Silver	3600	0.140
Steel, Mild	5920	0.233
Steel, Stainless	5800	0.228
Teflon	1400	0.060
Tin	3300	0.130
Titanium	6100	0.240
Tungsten	5200	0.200
Uranium	3400	0.130
Water	1480	0.584
Zinc	4200	0.170