



# OPERATION INSTRUCTION

## Measuring Tape



Code	Range	Graduation	Wide of tape
7140-3	0-3mm	1mm	±0.5mm
7140-5	0-5mm	1mm	±0.5mm
7140-8	0-8mm	1mm	±0.5mm

1. Before use, check that the tape is light, flexible and free from jamming when pulling out and winding in; the locking knob can effectively control the tape winding.
2. When using measuring tape, the "0" should be taken as the base point of measurement, so as to facilitate the reading.
3. When pulling out measuring tape, it should be kept straight and tightened.
4. The tape must be kept clean, and it should not be rubbed with the measured surface to prevent scratch.
5. When using measuring tape, do not pull out the tape too hard. Pull it out slowly, and let it winding in slowly when the measurement is finished.
6. The measuring tape can only be rolled and can't be folded. It's not allowed to be placed in damp and acid gases to prevent rust.

MN-7140-E

V0