


測量方法:



角焊縫厚度 (mm)	焊腳尺寸 (mm)	精度
4, 5, 6, 7, 8, 9, 10, 12	4, 6, 7.5, 10, 12, 14, 16, 18	±0.5mm