





OPERATION INSTRUCTION

Welding Gauge




Graduation	Accuracy
0.2mm	$\pm 0.3\text{mm}$



Measuring purpose



Reading: A means scale A, B means scale B, C means scale C



MN-4840-E

V1