




Measurement	Range	Graduation	Accuracy
convex weld size	4,6,8,10,12,14mm	—	±0.5mm
length	0 - 50mm	1mm	±0.5mm

- 1.The gage is used to measure convex weld sizes.
- 2.Measurement



For example: the size of convex weld in the above figure is less than 12mm