



# OPERATION INSTRUCTION

## MEASURING TAPE(ECONOMIC TYPE)

Graduation: 1mm



1. The product is used to measure the length of workpieces.
2. Measurement:
  - When using, gently pull out the tape until it reaches the desired length to avoid damaging the tape or box with excessive force.
  - When measuring, align one end of the tape with the starting point of the measured workpiece, and pull it along the surface of the workpiece in a straight line to the end point, ensuring that the tape is tightly attached to the surface of the workpiece.
  - When measuring, the tape can be fixed with locking button to read the result as needed.
3. Precautions:
  - When using a measuring tape , avoid bending or folding it to avoid affecting measurement accuracy.
  - Store the measuring tape in a dry, ventilated, and cool place.

MN-7147-C/E

V0